



Wheel cylinders

Description

Roadmaster's wheel cylinder range covers a vast array of passenger and commercial applications and are manufactured to OE quality levels. Our wheel cylinders ensure optimum brake performance after fitment.

Roadmaster #		Picture
RMNTD58WC	<i>NISSAN TIIDA W/ABS Replaces:IBS JB72117 Bore:5/8"</i>	
RM2352WC	<i>HIACE REAR WHEEL CYL 01/83 - 12/83 Bore:22.22 mm</i>	
RM2438WC	<i>TOYOTA LITEACE- YM (40/41) 3/86 - 09/88 TARAGO - CR21-01/84 - YR (21/22/31) TOWNACE - YR39/ Bore:20.64 mm</i>	
RM2439WC	<i>TOYOTA CROWN - MS (65/83/85) HIACE-LH (LH (51/61/71/103/113/125) RZH (103/113/125) YH (53/63/73) HILUX/4 RUNNER - RN (85/90) Bore: 23.81 mm</i>	
RM2517WC	<i>TOYOTA HILUX/4RUNNER RN-YN 01/80-87</i>	

	(31/36/41/46/57/60/65) -TARAGO-CR(21) TCR (10/11/20/21) YR (20/21/22/31) Bore:22.22 mm	
RM2524WC	Ford LASER-KA-KB-KC-KE/METEOR-GA-GB-GC/MAZDA 323 - BD (1.3)-BD (1.5) BF (1.6) / Bore:17.46 mm	
RM2669WC	EXCEL / COLT / LANCER / NIMBUS Bore:19.05 mm	
RM2686WC	HOLDEN RODEO - JACKAROO 81/03 Bore:25.40 mm	
RM2761WC	MITSUBISHI COLT 82-90 Bore:19.05 mm	
RM2797WC	TOYOTA L/CRUISER 80/95 Bore: 25.40 mm	
RM2820WC	MITSUBISHI-EXPRESS-SJ/ L200 - MC-MD L300 - SB- SC- SD- SE-SF-SG-SH PAJERO - NA-NB-NC-N/ STARWAGON - SJ Left Hand- Bore:20.64 mm	
RM2821WC	MITSUBISHI-EXPRESS-SJ/ L200 - MC-MD L300 - SB- SC- SD- SE-SF-SG-SH PAJERO - NA-NB-NC-N/ STARWAGON - SJ	

	<i>Right Hand- Bore:20.64 mm</i>	
RM2888WC	<i>TOYOTA RH COROLLA 85/01 Bore: 19.05 mm</i>	
RM2889WC	<i>TOYOTA LH COROLLA 85/01 Bore: 19.05 mm</i>	
RM2892WC	<i>HOLDEN RODEO 84/03 Bore: 22.22 mm</i>	
RM2893WC	<i>COURIER / ECONOVAN RWCYL Bore: 17.46 mm</i>	
RM2894WC	<i>COURIER / ECONOVAN RWCYL Bore: 17.46 mm</i>	
RM3024WC	<i>FORD MAVERICK-Y60/ PATROL-Y60 (GQ) PATROL - Y61 (GU)</i>	
RM3025WC	<i>MITSUBISHI TRITON RH 4WD 86/96 Bore: 22.22 mm</i>	
		


RM3026WC	<i>mitsubishi triton LH 4WD 86/96 Bore: 22.22 mm</i>	
RM3033WC	<i>DAIHATSU - CHARADE 87/93 Bore: 17.46 mm</i>	
RM3038WC	<i>FORD LASER/MAZDA 323 90/94 Bore: 17.46 mm</i>	
RM3042WC	<i>FORD/MAZDA R/H/R Bore: 17.46 mm</i>	
RM3043WC	<i>FORD / MAZDA L/H/R Bore: 17.46 mm</i>	
RM3064WC	<i>TOYOTA HI-LUX 4WD 86/04 Bore: 22.22 mm</i>	
RM3065WC	<i>TOYOTA CAMRY LH 93/95 LH 93/95 Bore: 20.64 mm</i>	
RM3066WC	<i>TOYOTA CAMRY RH 93/95 Bore: 20.64 mm</i>	
RM3068WC	<i>FORD FESTIVA/MAZDA 121 87/97 Bore: 15.87 mm</i>	

		
RM3077WC	<i>NAVARA / PATHFINDER RWCYL Bore: 23.81 mm</i>	
RM3084WC	<i>HONDA ACCORD- CB7 (2156 F22A3) Left/H CIVIC - ED/EG/EH/EJ/EK - HRV - HRV (1343CC)-(1493CC)-(1590CC) Bore:19.05 mm</i>	
RM3085WC	<i>HONDA ACCORD-CB7 (2156 F22A3) Rht/H CIVIC - ED/EG/EH/EJ/EK - HRV - HRV (1343CC)-(1493CC)-(1590CC) Bore:19.05 mm</i>	
RM3087WC	<i>HYUNDAI EXCEL / S COUPE RRH-WCYL Bore: 20.64 mm</i>	
RM3088WC	<i>HYUNDAI EXCEL / S COUPE RLH-WCYL Bore: 20.64 mm</i>	
RM3089WC	<i>HYUNDAI LANTRA 91/00 Bore: 19.05</i>	
RM3090WC	<i>HYUNDAI LANTRA</i>	

	91/00 Bore: 19.05	
RM3107WC	<i>DAIHATSU CHARADE</i> 87/93 Bore: 17.46	
RM3108WC	<i>NAVARA / PATHFINDER</i> W/Cyl LH/RH Bore: 20.64 mm	
RM3110WC	<i>SUZUKI VITARA</i> W/Cyl RH Bore: 23.81 mm	
RM3111WC	<i>SUZUKI VITARA</i> W/Cyl LH Bore: 23.81 mm	
RM3128WC	<i>MITSUBISHI TRITON</i> LH 91/97 Bore: 23.81 mm	
RM3129WC	<i>MITSUBISHI TRITON</i> RH 91/97 Bore: 23.81 mm	
RM3142WC	<i>MITSUBISHI LANCER- CB-CC-CE</i> <i>MIRAGE - CE/PROTON PERSONA/SATRIA/</i>	

	WIRA - 1468CC-(LH/RH) Bore:19.05 mm	
RM3143WC	HYUNDAI EXCEL W/Cyl LH - 94/00 Bore: 19.05 mm	
RM3144WC	HYUNDAI EXCEL W/Cyl RH 94/00 Bore: 19.05 mm	
RM3145WC	TOYOTA COROLLA LH 94/00 Bore: 17.46mm	
RM3146WC	TOYOTA COROLLA RH 94/00 Bore: 17.46mm	
RM3147WC	FORD FESTIVA /MAZDA 121 W/Cyl LH-RH 94/00 Bore: 17.46 mm	
RM3166WC	TOYOTA RAV 4 - SXA10 / SXA11- 07/94 - 08/00 (LH/RH) Bore:17.46 mm	
RM3169WC	KIA SPORTAGE W/Cyl LH-RH REAR Bore: 20.64 mm	

RM3170WC	<i>KIA MENTOR 12/96 - 06/00 SPECTRA- FB/ 05/01 - 12/01 LH/RH - Bore:19.05 mm</i>	
RM3171WC	<i>DAEWOO /HOLDEN W/Cyl LH-RH REAR Bore: 17.46 mm</i>	
RM3174WC	<i>FORD / MAZDA W/Cyl LH-RH REAR Bore: 19.05 mm</i>	
RM3178WC	<i>HOLDEN BARINA W/Cyl LH-RH REAR 94/03 Bore: 19.05 mm</i>	
RM3186WC	<i>NISSAN PULSAR W/Cyl LH-RH REAR 91/00 Bore: 15.87 mm</i>	
RM9545WC	<i>FORD TRANSIT W/Cyl LH-RH REAR Bore: 25.40mm</i>	
RM9548WC	<i>FORD COURIER/RAIDER - PD MAZDA B SERIES - B2500/B2600 Bore:20.64 mm</i>	
RM9550WC	<i>FORD COURIER/RAIDER - PD</i>	

	MAZDA B SERIES - B2500- B2600 <i>Bore:20.64 mm</i>	
RM9552WC	SUZUKI BALENO / LIANA <i>W/Cyl RH</i> <i>Bore: 17.46 mm</i>	
RM9553WC	SUZUKI BALENO / LIANA <i>W/Cyl LH</i> <i>Bore: 17.46 mm</i>	
RM9559WC	DAIHATSU SIRION / YRV <i>W/Cyl LH-RH REAR</i> <i>Bore: 17.46 mm</i>	
RM9622WC	FORD ESCAPE /MAZDA TRIBUTE <i>W/Cyl LH-RH REAR</i> <i>Bore: 23.81 mm</i>	
RM9676/7WC	HYUNDAI GETZ <i>W/Cyl LH-02/08</i> <i>Bore: 17.78mm</i>	
RM9678WC	SUZUKI GRAND VITARA <i>W/Cyl LH 01/05</i> <i>Bore: 22.22 mm</i>	
RM9679WC	SUZUKI GRAND VITARA <i>W/Cyl RH 01/05</i>	

	Bore: 22.22 mm	
RM9707WC	KIA RIO W/Cyl LH-RH REAR 02-05 Bore: 17.46 mm	
RM9710WC	HOLDEN RODEO W/Cyl LH-RH REAR 03/04 Bore: 25.40 mm	
RM9882WC	MAZDA 2 DY 2002-2006 Bore: 19.05mm	
RM9886WC	FORD RANGER W/Cyl LH-RH REAR 07/08 Bore: 23.81 mm	
RM9939WC	HOLDEN RODEO 03/05 W/Cyl LH-RH REAR Bore: 23.81 mm	
RM9949WC	CHRYSLER VOYAGER - GS 02/97 - 04/01 LH/RH Bore:19.05 mm	
RM9950WC	NISSAN PULSAR W/Cyl LH-RH REAR 01/04 Bore: 15.87 mm	

		
RM9975WC	<i>SUZUKI SWIFT RS415 W/Cyl LH-RH REAR 05/08 Bore: 19.05 mm</i>	
RM9976WC	<i>TOYOTA YARIS NPC91 W/Cyl RH 11/05– 12/06 Bore: 19.05mm</i>	
RM9977WC	<i>TOYOTA YARIS NPC91 W/Cyl LH 11/05– 12/06 Bore: 19.05mm</i>	
RM9978WC	<i>TOYOTA HI-LUX 2WD TGN16 W/Cyl LH-RH REAR 05/08 Bore: 22.22 mm</i>	
RM9979WC	<i>TOYOTA HILUX 4WD KUN/GGN W/Cyl LH-RH REAR Bore: 22.22 mm</i>	
RM10015WC	<i>HOLDEN BARINA -TK- (12/05 - 04/07) LH/RH -Bore:</i>	
RM10017WC	<i>FORD FAIRLANE/LTD - ZJ FALCON - XC- XD- XE- XF (& UTE) NISSAN XFN - XFN (UTE) 07/88 - 09/91 Bore:20.64 mm</i>	
RM10046WC	<i>HOLDEN TORANA/SUNBIRD - LH-UC COMMODORE - VB-VC-VH-VK-VL</i>	

	GEMINI -TD-TE-TF-TG - Bore:22.22 mm HOLDEN - HJ/HX/HZ/HK/HT/HG-HQ HQ/HJ/HX/HZ/WB (1 TON & STATESMAN)	
RM10129WC	NISSAN NAVARA D40 LH/RH Bore: 22.22 mm	
RM10160WC	HOLDEN- EJ/EH/HD/HR/HK/HT/HG TORANA/SUNBIRD - LC/LJ CAMIRA - JB/J/JE	
RM10177WC	TOYOTA HI-ACE KDH (200-223) W/Cyl LH-RH REAR 05/08 Bore: 28.57 mm	
RM10178WC	NISSAN TIIDA C11 W/Cyl LH-RH REAR 2/06-1/07 Bore: 17.46 mm	
RM10181WC	NISSAN NAVARAD22 4X2 W/Cyl LH-RH REAR 01/08 Bore:23.81 mm	
RM10183WC	NISSAN NAVARAD22 4X4 W/Cyl LH-RH REAR 01-08 Bore: 22.22 mm	
RM10202WC	MITSUBISHI TRITON 4X4 ML	

	W/Cyl LH-RH REAR 06/08 Bore: 21.75 mm	
RM10337WC	TOYOTA CAMRY W/Cyl LH 89/93 Bore: 19.05 mm	
RM10338WC	TOYOTA CAMRY W/Cyl RH 89/03 Bore: 19.05 mm	
RM17507WC	FORD / JEEP W/Cyl LH Bore:22.22mm	
RM17508WC	FORD / JEEP W/Cyl RH Bore:22.22mm	
RM34876WC	CHRYSLER / FORD W/Cyl LH-RH REAR Bore: 20.64mm	

