

| Roadmaster Part Number | Description                                                                                                                                     | Brake Master Cylinder Assy                                                            |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| <b>RM1762MC</b>        | <p>PAJERO-<br/>NE-NF-NG(10/87-05/91)<br/>TRITON -<br/>MG-MH-MJ (09/89-10/96)<br/>Bore: 23.81 mm</p>                                             |     |
| <b>RM1852MC</b>        | <p>HILUX/4 RUNNER<br/>LN (106/111)10/88-03/95<br/>LN (85/86) 08/95 - 11/97<br/>LN107 01/92 - 03/94<br/>Bore: 15.87 mm</p>                       |    |
| <b>RM1888MC</b>        | <p>CIVIC -<br/>ED/EG (1493CC)- EG (1343CC)<br/>CIVIC -<br/>EG/EH/EJ/EK (1590CC)<br/>Bore:20.64 mm</p>                                           |    |
| <b>RM1960MC</b>        | <p><b>Toyota Hiace</b><br/>Diesel <b>8/89-7/00</b> 3ltr LH103 113 125<br/>Petrol <b>8/89-7/00</b> RZH103 113 125<br/><b>(25.40 mm bore)</b></p> |   |
| <b>RM1981MC</b>        | <p>MITSUBISHI -<br/>GALANT- HG-05/89 - 08/90<br/>LANCER -<br/>CA- CB- CE- 04/89- 8/90-12/03<br/>Bore:22.22 mm</p>                               |  |
| <b>RM46010-EB328MC</b> | <p><b>NISSAN</b><br/>D40 NAVARA 06 – ON</p>                                                                                                     |  |
| <b>RM5489MC</b>        | <p><b>HOLDEN (EARLY)</b><br/>FC-HR DRUM+DRUM</p>                                                                                                |  |

| Roadmaster Part Number | Description                                                                                                                                                                                                                                                                                                                                                                                                                                           | Brake Master Cylinder Assy                                                            |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| RM7810MC               | LANDROVER 1" BORE                                                                                                                                                                                                                                                                                                                                                                                                                                     |    |
| RM9520MC               | <p><i>Toyota HILUX/4 RUNNER (25.40 mm bore)</i></p> <p>RZN147 ABS 11/97 - 10/01</p> <p>RZN149 ABS 11/97 - 10/04</p> <p>RZN154 ABS 01/98 - 10/04</p> <p><b>Toyota</b> Landcruiser Prado with ABS</p> <p>KZJ95 ABS 5 SP Man 03/00 - 02/03</p> <p>RZJ95 ABS 07/96 - 05/02</p> <p>VZJ95 ABS 07/96 - 02/03</p> <p>(25.40 mm bore)</p>                                                                                                                      |    |
| RM9524MC               | <p><b>Toyota Hilux</b> Non ABS (23.81 mm bore)</p> <p>2Dr C/Chas 97-02, 3RZ-FE 4Cyl</p> <p>RZN174R 2.7 MPFI Petrol 3RZ-FE 4Cyl</p> <p>VZN167R 3.4 MPFI Petrol, 02-05, 5VZ-FE V6</p> <p>VZN172R 3.4 MPFI Petrol 02-05, 5VZ-FE V6</p> <p>LN167R 3.0 Diesel 97-00, 5L 4Cyl</p> <p>LN167R 3.0 Diesel 00-05, 5L-E 4Cyl</p> <p>LN172R 3.0 Diesel 97-00, 5L 4Cyl</p> <p>LN172R 3.0 Diesel 00-05, 5L 4Cyl</p> <p>KZN165R 3.0 T/ Diesel 00-05, 1KZ-TE 4Cyl</p> |   |
| RM9726MC               | <p><b>HOLDEN</b></p> <p>RA RODEO 1" Bore STD PISTON</p>                                                                                                                                                                                                                                                                                                                                                                                               |  |
| RM9726EPMC             | <p><b>HOLDEN</b></p> <p>RA RODEO EXTENDED PISTON</p>                                                                                                                                                                                                                                                                                                                                                                                                  |  |
| RM9921MC               | HYUNDAI ELANTRA 00-03                                                                                                                                                                                                                                                                                                                                                                                                                                 |  |